



## Digital Semiconductor

### AlphaPC 164LX Motherboard Errata Sheet

June 11, 1997

Please be advised that the following issues pertain to the AlphaPC 164LX motherboard product:

- Compatibility problems exist between the AlphaPC 164LX motherboard and QLogic SCSI controller chips (ISP1020 and ISP1040).
- Due to the fact that we have not verified this product in server configurations, we do not recommend its use with multiple SCSI controllers or a Windows NT server.

DIGITAL recommends that you do not implement these configurations with the AlphaPC 164LX motherboard.

Please contact the following resources for questions and support:

| For documentation and general information...       | For technical support...                                |
|--|---|
| <b>Digital Semiconductor Information Line</b>      | <b>Digital Semiconductor Customer Technology Center</b> |
| United States and Canada: 1-800-332-2717           | Phone (U.S. and international): 1-508-568-7474          |
| Outside North America: 1-510-490-4753              | Fax: 1-508-568-6698                                     |
| Electronic mail address: semiconductor@digital.com | Electronic mail address: ctc@hlo.mts.dec.com            |

© Digital Equipment Corporation 1997. All rights reserved. Printed in U.S.A.  
 AlphaPC, DIGITAL, Digital Semiconductor, and the DIGITAL logo are trademarks of Digital Equipment Corporation.  
 Digital Semiconductor is a Digital Equipment Corporation business.  
 ISP is a trademark, and QLogic is a registered trademark of QLogic Corporation.  
 Windows NT is a trademark of Microsoft Corporation.  
 All other trademarks and registered trademarks are the property of their respective holders.

EC-R6XQA-TE